



**WITE32™**  
**Release Notes**

**Version 2.64**

**07/06/2001**

# CHAPTER 1

## INTRODUCTION

The 2.64 release incorporates the bug fixes introduced after WITE32 2.63 release. (This document uses WITE32 2.63 release notes as a base line for comparison.). This is mainly a maintenance release that fixes a few problems that affect only internal Guzik Technical Enterprises usage of the WITE32 software.

# CHAPTER 2

## FIXED BUGS

The following bugs were discovered in WITE32 ver.2.63 or earlier, and fixed in WITE32 ver.2.64. The description below explains the bug behavior as it appeared in WITE32 ver.2.63.

### 2.1 “Cannot send command to TMS” Bug

The “Cannot send command to TMS” error message pops up intermittently when executing a spinstand balancing test.

### 2.2 Head Amplifiers

Fixed bugs in the head amplifier drivers:

- VM5410D3 - The registers read-back function returns wrong values.

### 2.3 Miscellaneous

Several internal problems, which affect only internal Guzik Technical Enterprises usage of the WITE32 software, have been fixed.