



WITE32™
Release Notes

Version 2.66

08/16/2001

CHAPTER 1

INTRODUCTION

The 2.66 release incorporates the bug fixes introduced after WITE32 2.65 release. (This document uses WITE32 2.65 release notes as a base line for comparison.)

Fixed Bug

In the 2.66 release the bug related to micro positioning of the 1701B spin stand was fixed.

Copyright 2001 Guzik Technical Enterprises, Inc. All rights reserved.