



## Release Notes

# **WITE32**

**Version 2.72**

**07/05/2005**

# Table of Contents

<b>Chapter 1 Introduction .....</b>	<b>3</b>
<b>Chapter 2 New Hardware Supported in WITE32 .....</b>	<b>4</b>
2.1 New Head Amplifiers .....	4
2.2 New Revision of Spectrum Analyzer Board.....	4

# **CHAPTER 1 INTRODUCTION**

The release 2.72 of WITE32 incorporates new features introduced after the release 2.71. This document uses the release notes for WITE32 version 2.71 as a base line for comparison.

# CHAPTER 2

## NEW HARDWARE SUPPORTED IN WITE32

### 2.1 New Head Amplifiers

The following head amplifiers are supported for the first time in WITE32 version 2.72:

- PA7550
- SR1647
- SR1651AAA
- SR1984
- TC7547

### 2.2 New Revision of Spectrum Analyzer Board

The WITE32 version 2.72 supports the new revision “F” of the Spectrum Analyzer board *P/N 313990*. This revision of the Spectrum Analyzer board was not supported in the WITE32 version 2.71 and earlier versions of WITE32.

If you start WITE32 version 2.71 or earlier on a tester equipped with the new Spectrum Analyzer board, the following error message is displayed:

“Compatibility error: The board (SpAnHF P/N 313990) can not work with the current module revision 3. Please upgrade to revision >= 4.”